
Appendix

A - Existing Conditions Inventory


B - HQTA Toolkit





THIS PAGE HAS BEEN INTENTIONALLY LEFT BLANK

Appendix A Existing Conditions Inventory





Project Area

EXISTING CONDITIONS INVENTORY

- A Amtrak / Metrolink Downtown Station
- **B** City Hall
- Convention Center
- D Riverside Superior Court
- Main Street
 Pedestrian Mall


Metrolink Route
and Station



Study Area

Marketplace
Specific Plan Area






Activity Centers

EXISTING CONDITIONS INVENTORY

- A Downtown Riverside
- University of California -Riverside
- UC RiversideBotanic Gardens
- Riverside CityCollege
- Santa Ana River Trail



Source: Google Maps

Street Classification and Traffic Signals

EXISTING CONDITIONS INVENTORY

Arterials

- University
- Mission Inn
- Lime
- 14th
- 12th (west of SR-91)
- 10th (west of SR-91)



Rail crossing signal

Highway

Arterial

Collector

Local Street

Bridge





Access and Barriers

EXISTING CONDITIONS INVENTORY

SR-91 on- / off- ramp Vehicle Access

- 14th
- Mission Inn
- 10th Street (on-ramp)

SR-91 Crossings

- Mission Inn
- University
- 14th

Metrolink Corridor Crossings

- Metrolink station pedestrian bridge
- Mission Inn




←→ SR-91 crossing

W Barrier

Highway Access






Sidewalks

EXISTING CONDITIONS INVENTORY

Sidwalk Gaps

- Commerce
- Mission Inn
- 6th
- 5th
- Connecting Metrolink corridor to residential neighborhood to east



Walkshed and Connectivity


EXISTING CONDITIONS INVENTORY

Average block size:

4.49 acres

Number of intersections: 89

 Limited access to Downtown within 10-minute walk



1,000


500

2,000'

Public Transportation

EXISTING CONDITIONS INVENTORY

- Transit classification based on SCAG 2040 RTP/SCS
- Multiple bus lines follow Lemon/Lime -University - Vine - 14th Loop
- Multiple bus lines with stop at Metrolink Station (1, 15, 29, 49, 54, 208, 210, 212, 220)



Commuter Rail

Express Bus

Rapid Bus

Local Bus

0 500 1,000 2,000' **N**

Bicycle Facilities

EXISTING CONDITIONS INVENTORY

Proposed class II (bicycle lane):

- Park
- · Lime / Olivewood

Proposed bicycle route:

- 14th
- University (existing gaps in bike lanes)
- RTA First/Last Mile Mobility Plan

Existing


Bicycle Lane

Proposed

Bicycle Lane

Bicycle Route






Traffic Volumes

EXISTING CONDITIONS INVENTORY

 No traffic count information found for streets east of Metrolink corridor within study area (excluding 12th)

Traffic volume concentrations:


- 14th
- University
- Market



Less than 5k

2,000'

1,000



500

Vehicle - Bicycle / Pedestrian Collisions

EXISTING CONDITIONS INVENTORY

Collision concentrations:

- 14th
- University
- Mission Inn
- 14th / Victoria

Number of Crashes

- - 2
- - 3




- **Bicycle Fatal**
- Bicycle Injury
- **Pedestrian Fatal**
- **Pedestrian Injury**






Section A - A'



- 4 travel lanes
- Bus corridor
- On-street bicycle lanes
- Narrow sidewalks
- Additional turn lanes at intersections and freeway access points
- Depressed between Mulberry Street and Park Avenue











EXISTING CONDITIONS INVENTORY

Section A - A'



Commerce Stree

- 4 travel lanes
- Bus corridor
- On-street bicycle lanes
- Narrow sidewalks
- Additional turn lanes at intersections and freeway access points










Riverside Marketplace District Vision Plan

Commerce Street


EXISTING CONDITIONS INVENTORY

Section A - A'



- Utilization of rail spurs
- Use of Metrolink ROW

Vine Street - West










• Sufficient Capacity for Buses and Traffic?

Section A - A'












Section A - A'






SR - 91

- Pedestrian Bridge or Deck Park?
- Use Publicly-owned land west of 91 Freeway










Rail Lines and Truck Routes

EXISTING CONDITIONS INVENTORY

- No specific truck routes identified in General Plan
- SR-91 and access points to SR-91 mentioned as truck circulation routes



Rail line

0 500 1,000 2,000' N

Bridge

Open Space and Street Trees

EXISTING CONDITIONS INVENTORY

 Two open spaces within the 1/2 mile area

Street tree coverage concentration:

- Vine Street
- East of Park Avenue
- Downtown Riverside
- Condition, size, age, and species of street trees varies considerably




Existing Land Use

EXISTING CONDITIONS INVENTORY

- Light industrial immediately east of Metrolink corridor
- Single family located east of Metrolink corridor





General Plan Zoning


EXISTING CONDITIONS INVENTORY

Desired Parking ratios, Height, Density?



1,000


2,000'



Parking

EXISTING CONDITIONS INVENTORY


 Significant concentrations of surface parking within 1/2 mile area



Vacant and Publicly-Owned

EXISTING CONDITIONS INVENTORY

 Most vacant sites located around periphery of 1/2 mile area



Publicly-owned

Source: Google Maps, SCAG

Ownership

EXISTING CONDITIONS INVENTORY

Important stakeholders / ownerhsip?






Source: Google Maps, SCAG

Potential Development Opportunities

EXISTING CONDITIONS INVENTORY

Factors for identifying potential development sites:

- Surface parking
- Vacant
- Underutilized
- Located along commercial / industrial corridors
- Multiple contiguous parcels / large single parcel





Source: Google Maps

Architecture and Photo Inventory

EXISTING CONDITIONS INVENTORY

- Contemporary industrial showroom / manufacturing facility
- Contemporary noncontributing buildings
- Adaptive reuse of historical buildings
- Vacant historical buildings
- Commercial storefronts
- Single-family historic tract / cottage / bungalow homes




















EXISTING CONDITIONS INVENTORY

THIS PAGE HAS BEEN INTENTIONALLY LEFT BLANK